

0007

**PLATEAU MINING CORPORATION
WILLOW CREEK MINE
847 NORTHWEST HIGHWAY 191
HELPER, UTAH 84526
(435) 472-0475**

FAX : (435) 472-4782 (Accounting and Technical Services)

Imaging
CP007/038
Copy Daron

TO: DARON HADDOCK DATE: 2/19/01
DEPT: COAL PAGES: 2
FROM: Vicky MILLER (INCLUDING THIS COVER SHEET)
FAX No.: _____
SUBJECT: Extension to Address Deficiencies Associated
WITH WATER MONITORING AT WILLOW CREEK MINE
COMMENTS:

HARD COPY OF THE LETTER WILL FOLLOW IN
THE MAIL.

**PLATEAU
MINING
CORPORATION**

Willow Creek Mine
847 NW Hwy 191
Helper, Utah 84526
(435) 472-0475
Fax: (435) 472-4780

An affiliate of



February 19, 2001

Mr. Daron Haddock
Department of Natural Resources
Utah Division of Oil, Gas and Mining
1594 West North Temple
Suite 1210
Salt Lake City, UT 84114-5801

RE: Extension to Address Deficiencies Associated With Water Monitoring Changes,
Plateau Mining Corporation, Willow Creek Mine, C/007/038-AM00L

Dear Mr. Haddock:

Plateau Mining Corporation, Willow Creek Mine is requesting an extension of time to respond to the deficiencies associated with water monitoring changes to the mining permit. We have conversed with Mike Suflita, the reviewer concerning the extension. Due to his current situation he was unable to discuss his review and subsequent list of deficiencies until a later date. Therefore, we are requesting that the date for the submittal of the response be extended to April 16, 2001 by which time we will have had an opportunity to have the discussion with Mr. Suflita and address the deficiencies. }

Should you have any questions concerning this request, please contact myself or Johnny Pappas.
Thank you for your assistance in this matter.

Sincerely yours,

Vicky S. Miller
Environmental Specialist
(435) 472-4711